

SALT[♦]

A R C H I T E C T S

Annexure E – Graphic Record of Existing Building Condition




Figure 1 Diagram of Existing Building



Figure 2 Front Facade



Figure 3 Front Façade



Figure 4 Back Facade



Figure 5 Existing Roof Condition above proposed Projector Room



Figure 6 Existing Trusses to be preserved.



Figure 7 Existing Electrical Equipment and DB



Figure 8 Walls in Proposed Exhibition Space



Figure 9 Existing room to be converted to projector room.



Figure 10 Location of Proposed Exhibition Space



Figure 11 Existing walls proposed to be demolished to allow access to reception



Figure 12 Existing Garage, to be converted to reception.



Figure 13 Existing Pump Room Equipment



Figure 14 Location of proposed Heliostat Room



Figure 15 Location of Proposed Bathrooms



Figure 96 Existing Pump Room